



4-Wire RTD Configuration**Wiring Resistance Devices (Potentiometers)**

Potentiometer wiring requires the same type of cable as that for the RTD described on page 9. Potentiometers can be connected to the module as a 2-wire or 3-wire connection as shown below.

2-Wire Potentiometer Interconnection**NOTE**

The potentiometer wiper arm can be connected to either the EXC or return terminal, depending on whether you want increasing or decreasing resistance.